

# **“Statistical Process Control and Statistical Methods for Lean Systems”**

## *Contents*

1. Introduction to Continuous Improvement and Variation Reduction
  - 1.1 Why Reduce Variation?
  - 1.2 Cost of Variation – Relationships to Target
  - 1.3 Key Process Variables
  - 1.4 Assumptions at your company?
2. Understanding Natural Variation
  - 2.1 Group Exercise: “Deming’s Red Bead Box Experiment”
  - 2.2 Sources of Variation
3. Statistical Process Control (SPC)
  - 3.1 Estimating Natural Variation & Special-Cause Variation
  - 3.2 The Shewhart Control Chart (What is important to know?)
  - 3.3 Run Charts/Trend Analysis
  - 3.4 Control Charts – Important Considerations
  - 3.5 Specification Limits vs. Control Limits – Do Not Confuse the Two
  - 3.6 Control Charts (Attribute and Measurement Data)
  - 3.7 Seven Basic Tools
  - 3.8 Central Limit Theorem
4. Descriptive Statistics of the Process
  - 4.1 Estimating Process Center Line(s) or PCL
  - 4.2 Estimating Process Variation
  - 4.3 Power of the Graph (Histograms)
  - 4.4 Data Quality (Assumption often overlooked)
5. Understanding Key Process Relationships
  - 5.1 X-Y Scatter Plots
  - 5.2 Statistical Tools for Assessing Correlation
    - 5.2.1 The Sample Correlation Coefficient ( $r$ )
    - 5.2.2 Properties of  $r$
    - 5.2.3 Is  $r$  statistically significant?
    - 5.2.4  $t$  Distribution or “Student’s T Distribution”
    - 5.2.5 Is  $r$  statistically significant –  $t$ -tes
6. Is the Process Capable of Meeting Desired Specifications?
  - 6.1 Natural Tolerance vs. Engineering Tolerance
  - 6.2 Long-Term Capability
  - 6.3 Short-Term Capability

- 6.4 Engineering Tolerances and Estimation Percent out-of-specification
- 6.5 Exercise: Capability Analysis
- 7. Process Funneling – Increasing Variation by Over-Adjustment
- 8. Root Cause Analysis
  - 8.1 Pareto Principle – “The Pareto Chart”
  - 8.2 “Fish-Bone” or “Cause-and-Effect” (CE) or Ishikawa Diagrams
  - 8.3 Group Exercise: Developing a Fish-Bone Diagram
  - 8.4 Process Flow Mapping
  - 8.5 Value Stream Mapping
  - 8.6 Failure Mode and Effects Analysis (FMEA)
- 9. Measurement error – Gage R&R
- 10. PDCA – Plan-Do-Check-Act Cycle
- 11. Costing Variation (“Taguchi Loss Function”)
- 12. General Introduction to Lean Manufacturing
- 13. Lean Thinking, Lean Tools, and Theory of Constraints
  - 13.1 Lean Thinking – Eight Deadly Wastes
  - 13.3 Lean Thinking – Common Mistakes in Implementation
- 14. Six Sigma - Introduction
- 15. Lean Six Sigma – Introduction
- 16. Integrating Theory of Constraints and Lean Manufacturing
- 17. Lean Thinking – Tools
  - 17.1 Japanese Principle of 5-S
  - 17.2 SIPOC Diagrams Suppliers, Inputs, Process, Outputs, Customers
    - 17.2.1 How to Create a SIPOC Diagram
    - 17.2.2 SIPOC Essentials: Defines Output Gaps, Process Gaps and Input Gaps
    - 17.2.3 SIPOC Diagram Exercise
    - 17.2.4 SMED
      - 17.2.4.1 Implementing SMED
      - 17.2.4.2 Accelerate Process of SMED – Focus on People First
      - 17.2.4.3 SMED – Definition of Overall Equipment Effectiveness (OEE)
    - 17.2.5 Takt Time
      - 17.5.1 Takt Time – Production Example

17.5.2 Takt Time – Work Cells

17.2.6 Jidoka (自動化)

17.2.7 Kanban (看板 or カンバン)

18. Lean System Exercise

19. Lean Thinking, 5S Exercise – “Dot Game”

20. Developing an Improvement Plan – Seven Basic Premises

21. Case Study

22. Review of Statistical Software (*JMP 10.0; Minitab 16; Statistica 10.0; Excel Statistical Add-ons*)