

Contents

1. Introduction to Continuous Improvement and Variation Reduction ...

Bookmark not defined.

1.1 Historical Perspective	
1.1.1 Deming's (Shewhart's) Views and Influences (80s and 90s)	
1.1.2 Shewhart Cycle or " <i>Plan-Do-Check-Act</i> " (PDCA) Cycle.....	
1.1.3 Taguchi, Ishikawa and others (80s and 90s) <i>pre Six-sigma Era</i>	
1.1.4 "Six-Sigma" Quality (90s and 2000s).....	
1.1.5 Lean Six Sigma ('LSS') Era (2000s).....	
1.1.6 'Lean' and Taiichi Ohno.....	
1.2 Cost of Variation – Relationships to Target	
1.3 Key Process Variables	

2. Understanding Natural Variation

2.1 Group Exercise: " <i>Deming's Red Bead Box Experiment</i> "	
--	--

3. Quantifying Variation - Statistical Process Control (SPC) ...

3.1 Estimating Natural Variation & Special-Cause Variation....	
3.1.1 The Central Limit Theorem	
3.2 Probability Density Function.....	
3.3 The Shewhart Control Chart (<i>What is important to know?</i>).	
3.4 Run Charts/Trend Analysis	
3.5 Control Charts – Important Considerations.....	
3.6 Specification Limits vs. Control Limits	

4.Descriptive Statistics of the Process

4.1 Statistics that Estimate the “Central Tendency” of the Distribution of the Data

Exercise 4.1.1 for Measuring Central Tendency

4.2 Statistics that Measure the “Variation” of the Distribution of Data ...

Exercise 4.2.1: Statistics that Measure Variability

Exercise 4.2.2: Scale Effect on Statistics that Measure Variability

4.3 Power of the Graph (Histograms).....

4.4 Box Plots.....

4.5 Quantiles

4.5.1 Percentiles.....

4.5.2 Quantile or Q-Q Plots

4.6 Difference between “Statistical Estimates” and “Population Parameters”

4.7 Data Analysis in JMP 13 and Minitab 17

4.8 Enumerative and Analytical Statistical Studies.....

4.9 Select References.....

5. Control Charts

5.1 “*Measurement*” Data

5.2 “*Attribute*” Data.....

5.3 Control Charts *without* Subgrouping.....

5.3.1	“X-Individual and Moving Range” Control Chart (or “ImR”)
5.3.2	Exercise ImR Control Chart for “ <i>Mat Moisture</i> ”
5.4	Control Charts <i>with</i> Subgrouping
5.4.1	“X-bar and Range” Control Charts (or “ <i>X-Bar and R</i> ”)
5.4.2	Exercise: X-bar and R Control Chart.....
5.4.3	X-bar and s Charts
5.4.4	Control Chart for the Coefficient of Variation (CV)
5.5	Control Charts for Attribute Data
5.5.1	Formula for " <i>np chart</i> " control limits
5.5.2	Formula for " <i>p chart</i> " control limits
5.5.3	Charts for Nonconformities
5.5.4	Formula for " <i>c chart</i> " control limits
5.5.5	Formula for " <i>u chart</i> " control limits
5.6	Control Chart Guide
5.7	Developing a Control Chart in Minitab
5.8	Developing a Control Chart in JMP
	6."Run Tests" for Control Charts.....
	7.Capability Analysis
7.1	Natural Tolerance vs. Engineering Tolerance
7.2	Long-Term Capability
7.3	Short-Term Capability
7.4	Exercise: Capability Analysis.....
7.5	Engineering Tolerances – Percent ‘ <i>Out-of-Spec</i> ’

7.6 Capability Analysis in Minitab 17	17
7.7 Capability Analysis in JMP 13	13
8. Process Funneling – Increasing Variation by Over-Adjustment.....	
9.Data Quality Assessment (<i>Often overlooked</i>).....	
9.1 Descriptive Statistic (Good Starting Point for Data Quality Assessment)	
9.2 Data Quality Verification - “ <i>Differences Charts</i> ”	
9.3 ‘Difference Control Chart’ - Monitoring a “Difference” from Target, Specification, Calibration Check, etc.	
10.Toyota Production System (TPS) - “<i>Lean Thinking</i>”	
10.1 Three Specific Type of Waste	
10.2 Eight Deadly Wastes	
10.3 Lean Tools	
10.4 Lean is a “Building Block” Approach.....	
10.5 Value Stream Mapping (Key Lean Tool)	
10.6 The Value Added Ratio (VAR)	
10.7 25 Lean Tools (Alphabetic Order).....	
10.8 Lean Implementation – Common Mistakes!	
11.Gemba 現場 (“<i>Genba</i>”)	
11.1 Four ‘W’s’ before setting off on any Gemba Walk.....	

11.2 Glass Walls

12.Japanese Principle of 5-S.....

12.1 Shadow Boards: One Aspect of of 5-S

12.2 The Numbers Game

12.3 Red Tag System.....

12.4 Sustaining 5S – Audit Templates

13.“Theory of Constraints” (TOC) related to “Push vs. Pull” systems.....

14.Takt Time

14.1 Takt Time – WWII Production Example

14.2 Takt Time – Work Cells

15.TOC Exercise & “Pull Systems” (M&M Game)

16.Process Flow Mapping.....

17.SIPOC Diagrams Suppliers, Inputs, Process, Outputs, Customers.....

17.1 How to Create a SIPOC Diagram.....

17.2 SIPOC Diagrams Essentials: Defines Output Gaps, Process Gaps and Input Gaps...

17.3 SIPOC Diagram – *Technical Service Example*

17.4 SIPOC Diagram – *Preparation*

17.5 SIPOC Diagram – *Exercise*

18. Summary. Fish-bone Diagrams, Process Flow Mapping, SIPOC Diagrams, & VSM.....

19.Root Cause Analysis – Diagnosing Sources of Variation.....

19.1 Pareto Principle – “*The Pareto Chart*”

19.2 “Fish-Bone” or Ishikawa Diagrams.....

19.3 The ‘5 *Whys*’ - Lean Root Cause.....

19.3.1 How to Complete the 5 *Whys*.....

19.3.2 ‘5 *Whys*’ Examples

19.4 Group Exercise: Developing a Fish-Bone Diagram

19.5 Cause Mapping

19.6 *Kobetsu* - Lean “Individual or Focused”

Project Definition Sheets

20. Correlation Statistics for Linear Relationships

20.1 *XY Scatter* diagrams exercise

20.2 Sample ‘Linear’ Correlation Coefficient (*r*).....

20.3 Properties of *r*

20.3.1 Exercise – Correlation Coefficient Calculation

20.4 Is *r* statistically significant?.....

20.5 Hypothesis Testing

20.6 Level of Significance.....

20.7 *t* Distribution or “*Student’s t Distribution*”

20.7.1 Exercise – Correlation Coefficient Calculation	
20.7.2 One and Two-Tailed t-tests.....	
20.8 Correlation Coefficients and p-values in JMP.....	
20.9 Correlation coefficients and p-values in Minitab	
21. Simple Linear Regression.....	
21.1 Scatter Plot and Linear Fit	
21.2 Curvilinear Statistical Relations	
21.3 Regression Model	
21.4 Theoretical Regression Model – Simple Linear Regression (SLR)	
21.4.1 SLR – Meaning of Parameters.....	
22. Method of Least Squares - Estimation of Regression Function	
22.1 Least Squares Example.....	
22.2 SLR Example using JMP.....	
22.3 SLR Example using Minitab	
22.4 SLR Example using Excel (Office 2010)	
22.5 Simple Linear Regression – <i>Case Study</i>	
23. Seven Basic Tools	
24. Check Sheet	
24.1 Check Sheet Example	
25. Variation is Cumulative (Quincunx Experiment)	
25.1 Variation is Cumulative Example.....	

26. Components of Variance	
26.1 Exercise: Estimates of Components of Variance ($n = 6$).....	
26.2 Exercise: Estimates of Components of Variance Exercise ($n = 3$).....	
27. Taguchi Loss Function - Costing Variation	
27.1 Loss Function	
27.2 Exercise: Estimating Loss due to Variability	
27.3 One-sided Taguchi Loss Function – Larger the Better.....	
27.4 One-sided Taguchi Loss Function – Smaller the Better.....	
27.5 Mean-Squared Deviation (MSD) – Products Produced by More than one Factory	
27.6 Taguchi Loss Function Case.....	
28. Gage R&R - Variation of the Measurement Process	
28.1 Classic Gage R&R adapted using Wheeler Methodology.....	
28.2 Gage R&R Classroom Micrometer Exercise.....	
28.3 Minitab 17 Gage R&R Software Options and Example.....	
28.4 JMP 13.1 Example for Gage R&R	
29. Control Charts for Autocorrelated Data.....	
29.1 Exercise: Autocorrelated Data Set.....	
29.2 X-Individual Control Charts adjusted for lag-1 Autocorrelation	
29.2.1 Exercise: Control Chart adjusted for lag-1 autocorrelation	
29.2.2 JMP - Generating Autocorrelated Control chart using “Residuals”	
29.2.3 Minitab – Generating Autocorrelated Control Chart using Residuals	

30. Exponentially Weighted Moving Average (EWMA).....

30.1 Comparing the Individuals Control Chart to the EWMA Control Chart

30.2 Calculating the EWMA

30.3 Calculating the Control Limits for the EWMA Control Chart.....

30.4 EWMA – JMP Exercise

30.5 EWMA – Minitab Exercise

30.6 EWMA Control Limits when the Data are Autocorrelated.....

 30.6.1 EWMA Autocorrelated Data Exercise.....

31. Multivariate Control Charts - “Hotelling’s T^2 Statistic”

31.1 Hotelling’s T^2 Statistic and Control Limits for Individual Observations

31.2 Recall F- Distribution

31.3 Hotelling T^2 Exercise.....

 31.3.1 Hotelling’s T^2 Control Chart - JMP Example.....

 31.3.2 Hotelling T^2 Control Chart – Minitab Example.....

 31.3.3 Select Multivariate SPC References

32. Toyota Production System (TPS) - “Lean Thinking” More Tools

33. SMED

33.1 Implementing SMED.....

33.2 Accelerate Process of SMED – Focus on People First.....

33.3 SMED Example - *Setup Resource Consumption Analysis*

34. Overall Equipment Effectiveness (OEE)

35. Kanban (看板 or カンバン)	
35.1 Examples of Kanban.....	
35.2 Benefits of Kanban	
36. Jidoka (自動化)	
37. Poka Yoke	
38. Andon (アンドン, あんどん, 行灯) or “Visual Factory”	
39. Lean Thinking – “Dot Game”	
40. Why Lean Efforts Fail: Views from a 25-year plant leader	
50. APPENDIX – “Other Root Cause Tools”	
50.1 Failure Mode and Effect Analysis (FMEA)	